

700 West Mineral Ave
Littleton, CO 80120



Network Disclosure Announcement No. 779

Short Term Public Notice Under Rule 51.333(a)

**CenturyLink's Internet address: <http://www.centurylink.com/disclosures/>
Copper Retirements in Iowa, Minnesota, and Washington**

First Implementation Date: *November 15, 2014*
Original Date Posted: **September 11, 2014**

Summary: Copper Retirements are necessary to respond to various factors in the Outside Plant, including road construction, maintenance problems, and growth accommodation. Replacement cables may be either copper or fiber. Specific information will be provided with each disclosure.

**Locations, Timing of
Deployments & Interface
Requirements:**

The following gives additional details on the copper retirement(s):

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	Replacing
IA	Indianola INDNIACO	11-17-2014	439001	E.673732	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	Replacing
IA	Indianola INDNIACO	11-18-2014	439001	E.677081	Road move in the area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
IA	Indianola INDNIACO	11-18-2014	411022	E.677054	Road move in the area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
MN	Anoka ANOKMNAN	12-19-2014	120603; 120604; 120605	E.637081	Road move in the area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	Replacing
MN	Coon Rapids CNRPMNND	12-15-2014	221005	E.629484	Road move in the area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
WA	Vancouver North VANCWANO	11-15-2014	221011	E. 634785	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

Additional Information:

Any customer premises equipment vendor/manufacturer or enhanced services provider desiring additional technical information in conjunction with this Disclosure can contact:

Abdennaceur Boudhaouia
Regulatory Compliance Manager
303-707-8561 Jamal.Boudhaouia@CenturyLink.com